

Check list to check in BIOS for remote machine

Risk	Mitigation	
Remote switch off	power on schedule: everyday, 06h00	
Electricity flaps, flashes	On AC recovery: Power ON	
Keyboard disconnected	disable [] enable keyboard error detection	
Display disconnected	Attach HDMI or DP dummy stick to emulate display.	

Revision #1

Created 30 August 2026 13:11:29 by Anton

Updated 30 August 2026 13:13:34 by Anton